SAXTONS

Vehicle Details

Registration Number: MC23NRK	**VIN:**
Make/Model:	**Mileage: 7085**
Colour:	

Report Key:

- Satisfactory for mileage & age
- Attention
- N/A — Not applicable

All items will be ticked as passed unless they fail the check. If not fitted with the option a tick will indicate it has been checked. Note - This does not guarantee the option is fitted to the vehicle.

Exterior Checks

✓	Body Exterior	✓	Keys / Doors / Locks
✓	Panel Condition	✓	Paintwork
✓	Exterior Trim	✓	Fuel Filler
✓	Number Plates	✓	Charge Socket
✓	Roof Condition	✓	Windscreen & Glass
✓	Wiper Blade Condition	✓	Lights

Engine Compartment

✓	Battery Test	✓	Auxiliary Drive Belt(s) Condition
✓	Engine Oil Level & Leaks	✓	A/C Compressor & Components
✓	Engine Coolant Level & Leaks	✓	Bonnet Catch / Bonnet Hinges
✓	Antifreeze Concentration	✓	Fuel Pump / Lines / Connections
✓	Automatic Transmission Fluid	✓	Cold Start & Warm up
✓	Radiator Pressure Cap	✓	Excessive Fumes / Smoke
✓	Water Pump	✓	Engine Noise Level
✓	Coolant Hoses / Pipes / Connections	✓	Turbocharger / Supercharger
✓	Brake / Clutch Fluid Levels & Leaks	✓	Throttle / Brake / Clutch Linkage
✓	Power Steering Fluid Level & Leaks	✓	Engine & Transmission Mounts
✓	Washer Fluid Level & Leaks	✓	Radiator / Cooling Pack
✓	Timing Belt / Chain Condition	✓	Engine Covers

SAXTONS

Electrical Controls

✓	Ignition & Starting System	✓	Interior Lights
✓	Battery Charging System	✓	Sunvisor Mirrors Illumination
✓	Indicators / Hazzard Lights	✓	12 Volt Sockets
✓	Number Plate Lamps	✓	Phone Charging Mat
✓	Fog Lamps	✓	USB Sockets
✓	Brake Lights	✓	Media Sockets & Slots
✓	Rear Lamps	✓	Front & Rear Heated Screens
✓	Front Parking Sensors	✓	Heated Mirrors
✓	Rear Parking Sensors	✓	Heated Steering Wheel
✓	Door Locks & Central Locking	✓	Heated Seats
✓	Luggage Compartment Equipment	✓	Electric Seats / Memory Function
✓	Charging Port Operation	✓	A/C Seats
✓	Convertible Hood / Sunroof Operation	✓	Massage Seats
✓	In Car Entertainment	✓	Power Fold Mirrors
✓	Navigation System	✓	A/C / Climate Control Operation
✓	External Aerial	✓	Heater Fan / Blower Operation
✓	Door Puddle Lamps	✓	Window Wipers
✓	Mirrors Operation & Folding	✓	Window Washers
✓	Horn	✓	Electric Windows
✓	Switches & Controls	✓	Rear View Camera Operation
✓	Instruments Function	✓	Infotainment Speakers & Sound Control

SAXTONS

Interior Checks

✓	Check Service History	✓	Dashboard Condition
✓	Steering Wheel	✓	Air Vent Operation
✓	Steering Wheel Controls	✓	Door Trim Panels
✓	Seat Mechanisms	✓	Glove Box
✓	Carpet Condition	✓	Battery Charge Cable Present
✓	Door Fittings Condition	✓	Key Operation
✓	Headlining	✓	Door Locks & Handles Operation
✓	All Seat Belts	✓	Tool Kit & Tyre Inflation Kit
✓	Rear View Mirror	✓	Bonnet Closure Latch & Cable
✓	Seat Upholstery	✓	Luggage Compartment
✓	Door Seals	✓	Soft Materials
✓	Door Check Straps	✓	Plastic Trims
✓	Bonnet Pull Lever	✓	Ambient Lighting

Steering & Suspension

✓	Steering Joints	✓	Bump Stops
✓	Shock Absorbers & Dampers	✓	Wheel Hubs & Bearings
✓	Road Springs & Suspension Units	✓	Tie Rods & Anti-Roll Bar
✓	Self Leveling Suspension	✓	Suspension Arms
✓	Hoses / Pipes / Connections	✓	Links & Mountings
✓	Subframe Condition & Mountings	✓	Drive Shafts & Gaiters

Drivetrain

✓	Casings	✓	No Fluid Leaks
✓	Cable Adjustments	✓	Hydraulic System Function
✓	Linkages	✓	No Hydraulic System Leaks
✓	Drive Shaft Assemblies	✓	Component Mountings
✓	Propshaft Assembly & Universal Joints	✓	Gaiters
✓	Differential	✓	Electric Motors

SAXTONS

Fuel / Exhaust / Underbody

✓	Catalytic Converter	✓	Exhaust Pipes & Silencers
✓	Diesel Particulate Filter	✓	Exhaust Mountings & Clamps
✓	Exhaust Manifold	✓	Heat Shields
✓	Smoke from Exhaust	✓	No Evidence of Corrosion
✓	Chassis Members & Floor Pan	✓	Corrosion Protection
✓	Fuel Tank Condition	✓	Fuel Tank Breathers
✓	Fuel Tank Mountings	✓	No Evidence of Fuel Leaks
✓	No Evidence of Accident Damage	✓	Fuel Pipes & Filler Neck Fittings

Brake System

✓	Master Cylinder	✓	ABS System
✓	Fluid Leaks	✓	Servo / Power Brake System
✓	Brake Flexible Hoses	✓	Front Brake Disc Condition
✓	Hand Brake Operation	✓	Front Brake Pad Condition
✓	Parking Brake Operation	✓	Rear Brake Disc Condition
✓	Brake Caliper Movement & Condition	✓	Rear Brake Pad Condition
✓	Brake Pedal Linkage	✓	Rear Brake Drum Condition
✓	Brake Pedal Rubber	✓	Rear Brake Lining Condition
✓	Brake Line Condition & Connections	✓	Rear Wheel Cylinder Condition

Measurements

NSF Tyre	5.5	OSF Tyre	5.5
NSR Tyre	5	OSR Tyre	5
NSF Brake Disc	43.3	OSF Brake Disc	43.3
NSF Brake Pads	CHECKED	OSF Brake Pads	CHECKED
NSR Brake Disc	29.6	OSR Brake Disc	29.6
NSR Brake Pads	CHECKED	OSR Brake Pads	CHECKED
Spare Tyre (If fitted)	CHECKED	Tyre Inflation Kit Present	CHECKED

SAXTONS

Road Test & Final Checks

✓	Engine Operation, Performance & Idle	✓	4WD Operation & Performance
✓	Engine Noises Normal	✓	Clutch Operation & Performance
✓	Braking Performance, Vibration & Effort	✓	Auto Change & Kick Down Operation
✓	Suspension Noises Normal	✓	Cruise Control Operation
✓	Transmission Operation & Performance	✓	Final Drive Operation & Performance
✓	Hand Brake / Parking Brake Operation	✓	Road Holding & Handling
✓	Instrument Panel Operation & Warning Lamps	✓	Steering Wheel Alignment
✓	Engine Temperature & Control	✓	Steering Handling & Performance
✓	Cooling Fan Operation	✓	Tyre Noise & Vibration
✓	No Excessive Smoke	✓	Road Noise & Wind Noise
✓	Hot Restart	✓	Check / Confirm No Fault Codes Present